ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
14

Ward Name
Bagalakunte

Street ID
W0712, W0815, W0660, W0562, W0761

Street Name
NA

Significant Landmark
Bagalagunte

Segment No.
14/S-W0712/S045500

Total Length (m)
13.13

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	3.33	77.499722	13.052916	77.499753	13.052916	w0150	W0170
2	4.28	77.504430	13.051344	77.504469	13.051336	W0121	W0125
3	5.52	77.506561	13.047188	77.506548	13.047139	W0125	W0127

Work Details

History of Road / Lane / Circles

Name of the Work
CONSTRUCTION & REPAIRS TO CULVERTS

Sanctioned Estimated Amount (Rs.)
1200000

Sanctioned Year
2016

Year
2015 - 2016

Type of Work

Other Work Type

Tender
Tender

Work Details

Job No. / Work Code
014-16-000004

Work Order No.
EE/DD/WO/231/15-16

Work Order Date
24/03/2016

Period of Extention

Defect Liability Period From

Defect Liability Period To

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
N.Shivananda

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.
9901829745

E-Mail ID

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0712, W0815, W0660, W0562,

Field Inspection Details

Number of Trees	Any Other Information	Name
0		D.S.MANJUNATH

Date of Inspection

29/09/2016

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDDEGOWDA	29/09/2016	29/10/2016	COMPLETED
EE	SRINIVAS	29/09/2016	29/10/2016	COMPLETED
AEE	RANGASWAMY	29/09/2016	29/10/2016	COMPLETED
AE	D.S.MANJUNATH	29/09/2016	29/10/2016	COMPLETED
AE	D.S.MANJUNATH	29/09/2016	29/10/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0712, W0815, W0660, W0562,